Oil Field Environmental Incident Summary

Responsible Party: CRESCENT POINT ENERGY U.S. CORP. **Well Operator:** CRESCENT POINT ENERGY U.S. CORP.

Well Name: STATE 1-36H-156-98

Field Name: WHEELOCK Well File #: 19209

Date Incident:1/15/2016Time Incident:09:00Facility ID Number:County:WILLIAMSTwp:156Rng:98Sec:36Qtr:

Location Description:

Submitted By: Chris Noonan Received By:

Contact Person: Scott Van De Woestyne

555 17TH STREET, SUITE 1800

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

0.5 Barrels 0.5 Barrels 0.5 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/29/2016 Clean Up Concluded: 1/17/2015

Risk Evaluation:

None

Areal Extent:

30x120 sqft

Potential Environmental Impacts:

Misted staining on snow/soil on location/adjacent field.

Action Taken or Planned:

Crews to clean up impacted snow/soils.

Wastes Disposal Location: Secure 13 mile facility

Agencies Involved:

Updates

Date: 1/19/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater popoff, impacted the adjacent field according to the report. More follow-up required.

Date: 2/24/2016 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/24/2015 at 13:29, on location. Vegetation/ground off site to the south/southeast has no visible staining; however, one older snow pile has some faint discoloration. Any remaining staining should naturally attenuate.